Work Order ID 60441 Page 1 Weshesday, July 07, 2010 3:01:03 PM Item ID: DSI 9506-011 Accept Setup Start Revision ID: Item Name: Installation Modification Stop **Start Date:** 7/8/2010 Start Oty: 2.00 Cust Item ID: Required Date: 7/22/2010 Req'd Qty: 2.00 Customer: Reference: Run Start Process Plan: MF Date: (0-7-7. Tooling: Approvals: Date: Stop SPC (Y/N): Date: Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center ID Description **Run Hours** Code Qty Qty Number Stamp Draw Nbr **Revision Nbr** DSI 9506 Α 100 0.00 0.00 Memo Diolostzi Document Control Photocopy bluefile &type labels per PPP DSI 9506-011 CHG00i 110 Pick Kit 0.00 Packaging 0.00 Memo Packaging 120 QC4- 100% Inspect kits for completeness 0.00 Siolotzi QC Memo Quality Control

Dart Ae W/O:	TOSPACE EL	a ———		\\/	DK ODDED CH	ANGES					
DATE	STEP		WORK ORDER CHAN PROCEDURE CHANGE			ANGES	Ву	Date	e Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	Part No:		PAR #:	Fault Cate	gory:	N	ICR: Yes	No	DQA:	_ Date: _	,
	Reso	lution:	Disposition:			c	QA: N/C Closed: Date:				
NCR:				WORK ORDI	ER NON-CONFO	RMANO	CE (NC	R)			
DATE	STEP	De	scription of NC Section A	Initial Chief Eng	Corrective Action Action Descrip Chief Eng	Section B tion	Sign Dat	&	erification Section C	Approval Chief Eng	Approva QC Inspect
							ļ				1
						A					

NOTE: Date & initial all entries

[→] H:\fF®RMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 60441

Wednesday, July 07, 2010 3:01:03 PM



Page 2

Item ID:

DSI 9506-011

Accept

Setup Start

Stop

Revision ID: Item Name:

Installation Modification

Start Date:

7/8/2010

Start Qty: 2.00

Req'd Qty: 2.00

Cust Item ID:

Customer:

Reference:

Approvals: Process Plan:

Required Date: 7/22/2010

Date: _____ Tooling:

SPC (Y/N):

Date:

Date:

Start Run

Sequence ID/

Date:

Operation Description

Set Up/

Run Hours 0.00

Tool ID

Tool # Plan Accept Code Qty

Reject Qty

Insp. Number Stamp

130

Work Center ID

Packaging

Packaging

Memo

0.00

Identify and pack for shipping as per PPP DSI 9506-011

Location:

PPP rev:

Memo

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

Stop

Reject

DATE S			WORK ORDER	CHANGES					
DAIL	STEP	PRO	OCEDURE CHANGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					_				
Part No:		PAR #: Fault Category: Disposition:					A :		

NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B			Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	Approval QC Inspector				
ja-												
#		j										

NOTE: Date & initial all entres

Fig. H:\fPORMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print Wednesday, July 07, 2010 3:01:02 PM Work Order ID: 60441 , Parent Item: DSI 9506-011 Parent Item Name: Installation Modification Start Date: 7/8/2010 Required Date: 7/22/2010 Start Qty: 2.00 Required Qty: 2.00 Comments: IPP Rev:A new issue DD 10.03.18 verified by:JLM Component Item ID/ Replacement Mfg/ Bin Primary Item Name Last Route Unit of Item ID Qty on Qty per Kit Total Purch Item Location Qty Location Seq ID Date Measure Hand Issued Qty Issued Purchased No 110 Each 168.0000 Location Loc Qty Loc Code ST357 168 NAS1149D0463J Purchased 168 No 110 Each 12.0000 Location Loc Qty Loc Code ST351 12 Ď2274 108827 12 Manufactured No 110 Each 357.0000 Location Loc Qty Loc Code ST010 357 57912 137 59108 D2529 220 Manufactured 110 Each 338.0000 Washer

Location

58568

ST017

Loc Qty

338

338

Loc Code

Dart Ae	rospace	Ltd							•	
W/O:				WO	RK ORDER CHANG	ES				
DATE	STEP		PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector	
				,						
Part No):		PAR #:	Fault Cate	jory:	_ NCR: Yes	No DQA:	Date: _		
	R	esolutio	Disposition:			QA: N/C Closed: Date:				
NCR:				WORK ORDE	R NON-CONFORMA	ANCE (NC	₹)			
			escription of NC	Corrective Action Se		on B	Verification	Approval	Approva	
DATE	STEP		Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	Section C	Chief Eng	QC Inspecto	
			i							
_										
1 ,	1	1				1				

NOTE: Date & initial all entres

^{* ,} H:\fFORMS\Quality Assurance\ap iroved QA\NCRWO RevE

Wednesday, July 07, 2010 3:01:02 PM

Work Order ID: 60441

Parent Item:

DSI 9506-011

Parent Item Name: Installation Modification



D3171-1

MS21042L4

Manufactured

Purchased

No

No

110 Each

Location ST041

Loc Qty 13 13 110 Each Start Date: 7/8/2010 Start Qty: 2.00

Required Date: 7/22\(2010

Required Qty: 2/00

10-7-20

Loc Code

13.0000

4,410.000

Location	Loc Oty
ST300	4398
113422	68
114523	28
114718	302
,114784	2000
115108	2000
ST356	12
108145	12

Loc Code

		1						•
Dart Ae	rospace Lt	d						
W/O:			W	ORK ORDER CHANGE	S		ų.	
DATE	STEP	PRO	PROCEDURE CHANGE			Date Qty	Qty Approval Chief Eng / Prod Mgr	Approva QC Inspecto
				·				
Part No):	PAR #:	Fault Cate	egory:	NCR: Yes	No DQA:	Date: _	
	Reso	lution:	Disposition	on:	QA: N/C Clo	sed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORMAN	NCE (NCR)		
	T	Description of NC	Corrective Action Sect		ı B	Verification	Ammunual	Approva
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approva QC Inspecto
		1						

NOTE: Date & initial all ent ies

[.] H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D350-578 REV. F AND EARLIER AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D350-578 REV. 1 AND EARLIER

REF TCCA STC SH93-4 REF FAA STC SR00028NY REF FAA STC SR00028NY REF EASA STC EASA.IM.R.S.01389

REFERENCE ONLY

TO ENSURE COMPATIBILITY BETWEEN THE D350-578-011/-021 BEARPAW INSTALLATION AND EXISTING AERAZUR FLOAT SYSTEM, CUSTOMERS ARE ENCOURAGED TO PROCURE DSI-9506-011 KIT LISTED BELOW AND PERFORM THE FOLLOWING DEVIATIONS ON INSTALLATION. REFER TO FIGURE 1.

- 1. MOVE EACH D2432F/D2672F BEARPAW AFT BY 1.50" MAX;
- 2. SUBSTITUTE AFTMOST D2438 CLAMP WITH TWO D3171-1 ANGLES TRIMMED TO FIT THE AERAZUR FLOAT CLAMPS ON EACH D2432F/D2672F BEARPAW;
- 3. ADD EXTRA HOLES/COUNTERBORES (Ø0.260" THRU, C'BORE Ø0.930" x 0.300" DEEP FROM BOTTOM) ON EACH D2432F/D2672F BEARPAW TO MOUNT CENTER D2438 CLAMP TO CLEAR AFT CROSSTUBE SADDLE.

IN ALL OTHER RESPECTS, INSTALL THE D350-578-011/-021 BEARPAW INSTALLATION PER INSTALLATION INSTRUCTIONS D350-578 REV. F OR EARLIER.

PARTS LIST

QTY -011	PART NUMBER	DESCRIPTION INSTALLATION MOD KIT		
Х	DSI-9506-011			
4	D2274	RADIUS BLOCK		
. 4	D2529 /	WASHER		
4	D3171-1 ;	ANGLE		
4	AN4-12A	BOLT		
4	AN960JD416	WASHER		
4	MS21042L4	NUT		

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01

D. SHEPHERD (DE # 02)

10.02.26 CERT. NO .: SH93-4 ISSUE NO .:

A	NEW IS						
	HEVE	330E	MB	10.02.26			
REV.			DESCRIPTION	BY	DATE		
DESIGN		A	5711				
DRAWN			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA				
CHECKE	CHECKED 10		DRAWING NO.				
MFG. AP	MFG. APPR.		DSI 9506		REV. A HEET 1 OF 2		
APPROV	APPROVED		TITLE		SCALE		
DE APPE	DE APPR.		INSTALL MODIFICATION		NTS		
DATE	10.02	2.26	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLED ON THE EXPRESS COMMINON THAT IT NOT TO BE USED FOR ANY PURPOSE OR COYNED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT OF THE				